ECS Configuration Change Request

CCR No. 96-1135	Logged Date 9/30/96	Rev. -------- --	Request Type CCR

Priority Routine [X] Urgent [ ] Emergency [ ]	Affected Release	Change Class

Title Install the Second Sun RITS Client

Documents Affected VCATS Workstation Summary	Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference

RTM Change   [ ]   **Start New Baseline** [ ]

Problem
The second Sun RITS Clients is now here. It needs to be installed.

Proposed Solution
Install the new Sun client as 'cle10sun' the computer is a Sparc 20/71, 2/2GB disk, 96MB memory and a single FDDI board. The following software should be installed - Solaris 2.5.1, Sparcworks 3.1, C compiler 4.0, C++ compiler 4.1, DCE 1.1 core.

Sparcworks, C and C++ compilers were purchased for this computer and should be added to the license count.

Install the software but do not configure the computer into a DCE cell. Install in Rm. 1105

Impact Analysis:

Organizations Affected:

	BOO [ ]	Contracts [ ]	ESO [ ]	FOS [ ]	M&O [X]
QA [ ]	Rel. A [ ]	Rel. B [X]	Rel. IR1 [ ]	MRS [ ] SMO [X]	Subconts [ ]
A.1 [ ]	Other				

Cost:	None [X]	Small [ ] (Not exceeding $100,000)	Medium [ ] ($100,000 to $500,000)	Large [ ] (Over $500,000)

Schedule: None [X]   Other

Additional LOC _____   Man-Months _____

Materials

Originator C. Brown	Signature	10/27/96
		Date

Office MRS Office Manager	Signature	
		Date

Disposition   Approved [ ]   Approved w/Comment [ ]   Forward [ ]   Disapproved [ ]

Comments:

CCB Chairperson	Signature	Date